



FIG. 1




2/28

**FIG. 2**




**FIG. 3**



3/28

FIG. 4



4/28

**FIG. 5**






FIG. 6




*FIG. 7*



7/28


*Fig. 8*



APPROVED C.G.F.G.  
BY CLARKS IN CLASS  
DRAFTSMAN

8/28


## FIG. 9




1000746939 - 024302

9/28

**FIG. 10**





10/28

## FIG. 11

(ex)

WHEN  $It=0.0271$ ,  $Qt=0.0156$ ,  
 $M=2$ ,  $m=4$  HOLD

$$(At, Bt) = 32 \cdot (0.0271, 0.0156) \\ = (0.866, 0.5)$$

$$C=32 \rightarrow 2^5 \text{ (L=5)}$$


$N=1$  BECAUSE  $m=4$ ,  $L=5$  AT  $N=L-m$

$$N=1 > 0$$


$$(At', Bt') = (0.01355, 0.0078)$$


11/28

**FIG. 12**




**FIG. 13**






12/28

FIG. 14




13/28

**FIG. 15**




**FIG. 16**



14/28

**FIG. 17**



**FIG. 18**






FIG. 19



## FIG. 20



17/28

*FIG. 21*




FIG. 22






FIG. 23



APPROVED  
BY  
DRAFTSMAN

20/28

FIG. 24



1000446666 6666666666

FIG. 25




FIG. 26

22/28




FIG. 27





FIG. 28







**FIG. 29****FIG. 30**

FIG. 31



**FIG. 32**

**FIG. 33**